

Sirius Minerals Incident Flash

INCIDENT TYPE	OMEGA REFERENCE	DATE OF INCIDENT	INCIDENT TITLE
Crush Injury	REP-18-000583	16 th July 2018	Plant/person contact
DESCRIPTION OF INCIDENT		POST INCIDENT MANAGEMENT	
<p>Zublin (Strabag Piling Contractor) were carrying out piling activities in Zone A of the Wilton Site. Whilst the Rig Operator was slewing the Piling Rig, the Rig Handler (Banksman) was caught between the rig and the casing resulting in the IP sustaining injuries that required Air Ambulance support and transfer to A&E.</p>		<ul style="list-style-type: none">) All Works on site stopped until further notice) All relevant parties informed of incident) Mines inspectorate (HSE) informed) Investigation begun including taking witness statements and breathalysing those involved 	
			
<p>Wilton Site, Zone A, showing the Piling Rig and where the IP was located prior to the incident</p>	<p>Piling Rig & Piling Steel Casing</p>	<p>Person caught between the rear of the rig and casing as displayed above</p>	
AREAS OF FOCUS / NEXT STEPS		AREAS FOR REVIEW	
<ul style="list-style-type: none">) Thorough Investigation to be carried out by the Principal Contractor with involvement from Sirius Minerals and specific external personnel.) No further work to begin until Review of all activities with Zone A work area has been carried out.) Briefing to all Site Personnel prior to work recommencing with the focus on Plant and Personnel interaction 		<ul style="list-style-type: none">) A review of the Piling Safe System of Work to be carried out) Functionality and Engineering Controls of Piling Rig) Training & Competency) Review of site safety behaviour 	

